

# 석면비산측정 결과보고서

- 도초 테마가 있는 웰빙소공원  
[수국공원(수국온실)조성]지정폐기물 철거공사 -



[별 첨1] 측정 위치도(측정 장소)

전라남도 신안군 도초면 도초서길 246-11



범 례



부지경계선

\*NO


시료채취

[별첨2] 측정 결과

2014. 09. 26.					
측정위치		측정시간(분)	유량(l/min)	측정농도 [기준: 0.01개/cm <sup>3</sup> ]	초과여부
*1	부지경계선1	10:00 ~ 14:02	9.93	불검출[검출한계 0.002미만]	미만
*2	부지경계선2	10:02 ~ 14:04	9.94	불검출[검출한계 0.002미만]	미만
*3	부지경계선3	10:04 ~ 14:06	9.92	불검출[검출한계 0.002미만]	미만
*4	부지경계선4	10:06 ~ 14:08	9.96	불검출[검출한계 0.002미만]	미만
*5	작업장주변	10:10 ~ 12:12	9.94	0.002	미만
*6	위생설비입구	10:13 ~ 10:55	9.93	불검출[검출한계 0.002미만]	미만
*7	폐기물야적	10:16 ~ 10:58	9.94	0.002	미만

[별첨3] 측정 사진

2014. 09. 26.

2014. 09. 26.				
				
*1 부지경계선1	*2 부지경계선2	*3 부지경계선3	*4 부지경계선4	*5 위생설비입구
				
*6 작업장주변	*7 폐기물야적			